



Original Schmidt OS8000 Silver Schmidt OS8200 Tutorial 02

Hammer controls

Identical operation




Original Schmidt OS8000




Silver Schmidt OS8200

Power ON / OFF



 **Press – ON**

Press and hold > 5s – OFF

 **Press – ON**

Press and hold > 5s – OFF

Back light ON / OFF



Press and hold > 1.4s - ON

Press and hold > 1.4s - OFF

Quick start a new series



Press and hold > 1.4s

Operation possible at any time


Current series is saved

New series is started


Menu navigation






Scroll 



Select 



Mode selection (Print versions only)






Scroll



Select

Standard selection





Scroll







Select

Clear memory




Any unsynchronized data will be lost

Info



Serial number
Firmware version






Measurement



Viewing Results

Scroll through results

Return to series



Delete whole series





Start new series

No. of impacts

Printing Results

Scroll through results

Return to series



Time out

No activity > 5 minutes

- **Power off**
- **Current series is saved**
- **Current series is closed**